

25X1

S E C R E T
SECURITY INFORMATION

REPORT

25X1

COUNTRY Czechoslovakia
SUBJECT Zbraslavice Airfield

DATE DISTR. 31 Aug. 53

NO. OF PAGES 2

NO. OF ENCLS. 1
(LISTED BELOW)SUPPLEMENT TO
REPORT NO.

25X1

PLACE
ACQUIREDDATE
ACQUIRED

DATE OF IN

THIS IS UNEVALUATED INFORMATION

25X1

1. The Zbraslavice Airfield /4949N-1512E7 was located two kilometers east of the center of Zbraslavice

25X1

2. The airfield was 900 m. long, northwest to southeast, and 700 m. wide, northeast to southwest; it was 481 m. above sea level. It had an irregular shape; the surface was level and grassy with natural drainage. No runways as such were marked off on the grassy area. A hangar was located on the east side of the airfield, and an apron surrounded the hangar. Two other buildings were located near the hangar

25X1

Airfield obstructions included: rolling hills surrounding the airfield (elevation unknown to me); power lines (4,000 v) 10 m. high, 500 m. to the north; power lines (4,000 v) 10 m. high, located 800 m. northwest; and trees 20 m. high located 250 m. northeast of the airfield.

3. The Zbraslavice Airfield was controlled by CSA.

25X1

the CSA air taxi pilots' school moved to Zbraslavice Airfield in 1952. Fischer Storch aircraft flying around Zbraslavice in the fall of 1952. (Fischer-Storch aircraft were used by CSA for training pilots for air taxis and crop dusting.)

USAF review completed.

S E C R E T

SECURITY INFORMATION

25 YEAR RE-REVIEW

25X1

Page Denied